



I print this on a sheet of Avery Label Paper and stick it on a manila folder.
 I cut it to size and mount it on a Dremel cut-off wheel mandrel and set it in the chuck.
 Using the 60hz fluorescent work light on my lathe table, I watch for the bands to "stop" for each of the low RPM's.



50
60
70
80
90
100
110
120
130
140
150
160
170
180
180
170
160
150
140
130
120
110
100
90
80
70
60
50
190
200
210
220
230
240
250
260
270
280
290
300
310
320
320
310
300
290
280
270
260
250
240
230
220
210
200
190